





$\frac{3}{4}$ in MAX GAP SIZE

.036 in STAINLESS STEEL

TKGAPFILLER25
Stove Gap Filler
8/5/2025

SUMMIT

FELIX STORCH, INC.
www.summitappliance.com
718-893-3900